

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0000013302	REPAIR OR REPLACE EXISTING ROOF
0000154571	REPLACE EXISTING LEVER DEVICES WITH LOCKNETICS PANIC BAR OR PUSH BUTTON DEVICE
0000298913	REPAIR DISTRIBUTOR HEAD IN SECTION 5 OF COOLING TOWER AND REPLACE EXISTING SLUICE GATE IN COOLING TOWER PIT
0000333485	REMOVE EPDM ROOF MEMBRANE AND APPLY A FLUID APPLIED ELASTOMERIC COATING
0000356913	REPLACE STEAM PIPING, CONDENSATE PIPING AND ASSOCIATED PUMPS
0000412763	REPLACE CHILL WATER MAIN TRUNK LINE
0000416549	PROVIDE LABOR & MATERIAL TO DISCONNECT AND RELOCATE GOVERNMENT EQUIPMENT FROM PRESENT LOCATIONS AND RECONNECT TO PROVIDE UTILITIES
0000462924	DESIGN AND INSTALL A SECURE PERIMETER
0000464664	ESTABLISH REGULAR SCHEDULED MAINTENANCE FOR DYNAMIC OVERHEAD CRANE
0000502397	REPLACE BALLAST AND LAMPS
0000505755	PROVIDE SAFETY RESTRAINT DESIGN SUPPORT & CONSTRUCT FOR BUILDING CRANE OPERATIONS
0000535948	REPLACE THE EXISTING CONTROL AIR COMPRESSOR AND AIR DRYER
0000536133	PROVIDE INPUT/OUTPUT POWER AND UCS MONITORING CIRCUIT FOR FERRUPS UPS EQUIPMENT
0000537870	REPLACE ROLL-UP DOORS#7, 8, 9, 10, 11, 12, 13, 15, 16, 18, 20, 22
0000546962	INSTALL SAND FILTRATION SYSTEM DESIGNED ON FWR 78757
0000547067	REPLACE EXISTING CONTROL AIR COMPRESSORS W/AIR DRYER AT 4628, 4646, 4660, 4642, 4605, 4653, 4653, 4654, 4656, 4659, 4674, 4583
0000547068	REPLACE EXISTING CONTROL AIR COMPRESSORS W/AIR DRYER - SEE LIST (10 TOTAL)
0000625678	REPAIR BROKEN CONCRETE SIDEWALKS THROUGHOUT THE 4200 COMPLEX
0000630670	REPLACE 1400 SQ FT OF NONREPAIRABLE RAISED FLOORS
0000648537	PERFORM REPAIRS NECESSARY TO CORRECT GENERAL SAFETY DEFICIENCY AT TEST STAND
0000655050	REMOVE BUMPER BLOCKS, GRADE SMOOTH, ASPHALT, STRIPE AND REINSTALL BUMPER BLOCKS ON PARKING LOT ON SOUTH SIDE OF BLDG
0000667045	REFURBISH TEST CELL AREA TO BE ACCEPTABLE FOR OFFICE SPACE IN THE 1101 AREA
0000680174	INSTALL A FLOW MEASUREMENT WEIR WITHIN MANHOLE #39 ALONG THE INDUSTRIAL SERVER
0000686201	PROVIDE FOR THE REPLACEMENT OF 23 SIEMENS MODEL 4700 KW METERS

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0000686278	REPLACE CHILLER
0000686467	PRESSURE WASH AND RECOAT FOAM ROOF WITH SILICONE COATING AND REPLACE 5 TURBINE ROOF VENTS, PAINT ROOF HATCH HANDRAILS, INSTALL A FIXED LADDER UP TO ROOF HATCH, INSTALL NEW FALL PROTECTION CABLES
0000699051	PROVIDE PDA-BASED MAINTENANCE SYSTEM FOR MSFC
0000699279	INSTALL BALANCING DAMPERS
0000699282	REMOVE AND REPLACE PIPING, VALVES , TRAP ASSEMBLIES AND THE STEAM DRIVEN CONDENSATE PUMP IN THE PIT
0000704805	PERFORM REPAIRS NECESSARY TO GENERAL SAFETY DEFICIENCY ITEMS 1 AND 2 AT TEST STAND
0000709296	REMOVE 2 OUTSIDE AIR DUCT RISERS FOR ACCESS TO AND SEAL CURTAIN WALL PENETRATIONS AROUND
0000709493	EQUIP 1 NEED THE HEPA FILTER THAT IS ON OUR HOOD IN ROOM 104 REPLACED. THE FILTER IS LOCATED IN THE EQUIPMENT ROOM
0000722105	PAINT HAND RAILS
0000727911	BRING CURRENT TRAFFIC CONTROL SIGNS AND POSTS TO CURRENT MUTCD STANDARDS.
0000727912	COAT HAZARDOUS WASTE STORAGE AREAS WITH IMPERVIOUS MATERIAL, BLDGS 4635, 4632 & 4633
0000732798	REPLACE THE STEAM AND CONDENSATE SYSTEM, THE HEATING AND COOLING COILS
0000732800	PAINT EXTERIOR WALLS OF PENTHOUSE AND ELEVATOR SHAFT
0000746134	DESCALE AND FLUSH THE HOT WATER SYSTEMS AT THE FOLLOWING LOCATIONS: 4610(E1, E2), 4663 (E1), 4612 (E5 E6) 4583 (E1) 4570 (E1 E2) 4561 (E1) 4653 (E1 E2) 4674 (E2) 4605 (E1)
0000749769	PROVIDE AND INSTALL 2 ROOM TEMP SENORS AT LOCATIONS OF ABANDONED PNEUMATIC THERMOSTATS ON NORTH WALL OF HIRAY
0000752574	POWER WASH & PAINT 2600 FT OF ROOFING SYSTEM AND REPLACE 3 BOILER STACKS (LABOR ONLY)
0000752791	FABRICATE 12" WIDE RIDGE CAP FOR BOTH SECTIONS OF BLDG ROOF, RECAULK ALL OF COUNTER FLASHING, REFASTEN ALL OF COPING AND SEAL AROUND PENETRATIONS
0000752920	CAULK AROUND WINDOWS, ALL PANELS AND COLUMNS ON EAST FACADE
0000773146	PROVIDE AND INSTALL REMOTE MONITORING VIA UCS FOR THE GAS DETECTION SYSTEMS: 4487BC-ODT0001, 4487BC-ODT0002 4487B-ODT0001 4650-ODT0003 4656-ODT0001 & 4708-ODT0035
0000779181	REPLACE FORMICA ON WALL PANELS IN ALL ELEVATORS IN 4200 , 4201 & 4202
0000784373	REWORK DISCHARGE PIPING FROM 2 OVERPRESSURE RELIEF VALVES ON STEAM PRESSURE REDUCING STATION
0000791563	PROVIDE TEMPORARY BOILER IN SUPPORT OF COF PROJECT
0000799765	PURCHASE & REPLACE 3 DELTA F O/2 CELLS FOR RMS 120,120F & 142

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0000799845	PURCHASE RCM PERFORMANCE EVALUATION
0000806288	PERFORM PHASE II - REPAIR AND RENOVATIONS - SCOPE OF WORK INCLUDES: REMOVAL AND REPLACE CU., STEAM COLIS AND REINSULATE UNITS. REMOVE/REPLACE ALL LIGHTS FIXTURES, REPAIR & REPAINT WALL, DOOR JAMS & WINDOWS. REMOVE, DISPOSE OF AND REPLACE CEILING /CARPET
0000806541	REPLACE 200 ELECTRICAL POWERED EXIT LIGHTS FOUND TO BE DEFECTIVE DURING THE ANNUAL SAFETY WALK WITH A SELF-POWERED 20 YR MAINTENANCE & ENERGY FREE EXIT LIGHT
0000811593	REPLACE APPROX. 200 FEET OF BUSS DUCT LOCATED IN THE NORTH HIBAY AREA. BUSS SHOULD BE 3 PHASE, 4 WIRE WITH REQUIRED VOLTAGE. REPLACE ALL 4 BUSS BARS USING A NEW BUSS DUCT
0000811671	CHECK FOR SOURCE OF WATER SUPPLY DRAINING INTO ABANDONED MAN HOLE, REROUTE DRAIN.
0000834244	PROVIDE PROPER LIGHTING FOR PARKING LOT
0000840780	INSTALL REMOTE ACCELEROMETERS ON FAN AND MOTOR POINTS TO PERFORM VIBRATION ANALYSIS ON 5 AH UNITS. 4708B-AH0021 4708B-AH0019 4708B-AH0018 4708B-AH0009 4708B-AH0006
0000840784	INSTALL REMOTE ACCELEROMETERS ON FAN AND MOTOR POINTS TO PERFORM VIBRATION ANALYSIS ON 7 AH UNITS. 4663A-AH0001 4663C-AH0004 4663A-AH022B 4663M-AH0001 4663A-RAF021A 4663C-AH0001 4663C-AH0008
0000846374	REPLACE THE UNDERGROUND STEAM AND CONDENSATE LINES FROM 4675 TO THE PIT, REPLACE THE STEAM DRIVEN CONDENSATE PUMP AND PIPING IN THE PIT AND SEAL WELD ALL ABANDON PIPING IN THE PIT
0000846411	REPLACE THE STEAM DRIVEN CONDENSATE PUMP AND PIPING
0000846543	PROVIDE AND INSTALL POLES AND LIGHTS FOR PARKING LOT IN THE GRAVEL SURFACE AREA
0000853209	PROCURE COOLING TOWERS FOR 4663
0000853329	INSTALL CATCH BASIN WITH DRAIN IN FRONT OF NORTH EAST PERSONNEL DOOR
0000853489	REPLACE STEAM LINE AND HEATERS
0000864501	REMOVE EXISTING TRANSITE ROOF PANELS OVER SCREENED IN TEST AREA AND INSTALL METAL FRAMING AND INSTALL METAL ROOF PANELS
0000864570	SEAL ALL BLOCK WALLS TO PREVENT EXTERIOR MOSITURE PENETRATION.
0000869284	REPLACE POCKET FILTERS IN ALL AIR HANDLERS
0000869291	REPLACE WATER COOLERS AND WATER FOUNTAINS - 4718,4728,4739,4752,4755 & 4759
0000869294	REPLACE WATER COOLERS AND WATER FOUNTAINS - 4200,4201,4202,4207,4249 & 4353
0000869296	REPLACE WATER COOLERS AND WATER FOUNTAINS - 4610,4619,4605,4653 & 4663
0000869304	REPLACE WATER COOLERS AND WATER FOUNTAINS - 4561, 4570 & 4666
0000869307	REPLACE WATER COOLERS AND WATER FOUNTAINS - 4436, 4493, 4628, 4702 & 4708
0000869560	REPLACE DOOR AND THRESHOLD ON DOOR #4 ON SOUTHEAST SIDE OF BLDG

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0000876379	REPAIR REPLACE ALL EXTERIOR DOORS
0000876830	INSTALL REMOTE DIFFERENTIAL PRESSURE SWITCHES ON FAN FILTERS BANKS-4708C-AH0020-RM241, 4708C-AH0021-RM241, 4708B-AH0021-RM1256,4708A-AH0013-RM1108, 4708A-AH0020-RM1264, 4708A-AH0023-RM1234, 4708A-AH0025-RM1210, 4708A-AH0026-RM1210, 4708C-AH0002-RM125A
0000876831	INSTALL REMOTE DIFFERENTIAL PRESSURE SWITCHES ON FAN FILTERS BANKS-4708A-AH0012-RME23, 4708B-SAF0001-MEZZ, 4708B-SAF0002-MEZZ, 4708B-SAF0003-MEZZ, 4708B-AH0001-HIRAY
0000876874	REPLACE CHILL WATER COILS
0000888398	REPLACE THE EXISTING ROLL-UP DOOR AND OPERATOR
0000888441	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED
0000893641	REPAIR LIGHTING
0000893642	REPLACE ALL HALL CALL ELEVATOR PUSH BUTTONS - BLS 4202 & 4201
0000893659	REPLACE THE EXISTING PUMPS AND TANKS
0000893773	REPAIR UNEVEN FLOOR THAT IS A TRIPPING HAZARD IN EGRESS ROUTE. HAZARD IS GREATER THAN 1/4 IN. DIFFERENTIAL IN FLOOR LEVEL
0000894077	SFN (RM 130, PNL0003 11265, RM130, PNL0004 11266) - LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED.
0000894079	REPLACE THE STEAM COIL OVER THE ROLL-UP DOOR ON THE WEST END OF RM
0000900218	PROVIDE LABOR AND MATERIAL TO REPLACE EXISTING FIRE ALARM SYSTEM
0000900329	REMOVE THE 4 EXISTING SUPPLY AIR REGISTERS CLOSER TO CENTER OF ROOM AND ADD NEW DUCT AND 4 ADDITIONAL SUPPLY REGISTERS
0000900458	PAINT LIME SILOH AND ADDITIONAL TANKS AND FABRICATE SIGNS TO BE INSTALLED ON TANKS
0000900465	REPLACE THE EXISTING ROLL-UP DOOR AND OPERATOR
0000907300	PROVIDE LABOR AND MATERIAL TO REPAIR AND REPLACE DETERIORATED TILES IN HALLWAYS AND LAB AREAS
0000907514	REPLACE CONTROL VALVE AND CONTROLLER ON MAIN STEAM LINES - BLDGS 4723 AND 4475
0000907538	THE EXISTING EMERGENCY ESCAPE STAIRS ARE TO BE REMOVE AND DEMOLISHED AND ONES INSTALLED
0000907568	PROVIDE LABOR & MATERIAL TO REPLACE EXISTING PLASTER CEILING IN ROOM 323 AND ADJACENT ROOMS. REMOVE PLASTER CEILING AND INSTALL NEW DROP CEILING TO INCLUDE FRAMES AND ACOUSTICAL TILE CEILING
0000909042	IMPLEMENT 480 VOLT MODIFICATIONS MADE NECESSARY BY ARMY CHANGEOUT OF 4160 VOLT PRIMARY BLDG TRANSFORMERS TO 12470 VOLT
0000910875	INSTALL VARIABLE FREQUENCY DRIVE ON HELIUM ARGON COMPRESSOR IN 4655 THAT WILL ALLOW THE MOTOR TO RUN AT LOWER SPEEDS

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0000914119	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED (83 PANELS)
0000914224	REPLACE BREAKERS FOR NORMAL POWER TO PABX TRANSFER SWITCH AND TO BLDG EM POWER TRANSFER SWITCH
0000914225	REPLACE PANEL NUMBERS 0006, 0010, 0012, 0014, 0015, 0013, 0011, 0009, 0008 & 0007
0000914321	REPAIR/ REPLACE METAL DOORS
0000920473	REPAIR PIPING LEAKS THROUGHOUT BUILDING. EXTEND ALL EQUIPMENT TO BUILDING DRAINS.
0000920508	INVESTIGATE SOUTH ACTUATOR COUPLING PROBLEM. REMOVE ACTUATOR AND INSPECT BEARINGS. REPLACE IF NEEDED. REPLACE COUPLING SPIDERS, ACQUIRE AND REPLACE BALL NUTS ON BOTH ACTUATORS. INVESTIGATE ALIGNMENT OF BOTH ACTUATORS FOR THIS JOINT
0000920529	REMOVE AND REPLACE STEAM COIL
0000920590	REPLACE AND RELOCATE HUMIDIFIER
0000920630	REPLACE STEAM AND CONDENSATE LINES AND UNIT HEATERS THROUGHOUT BUILDING
0000920638	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED (4 TOTAL)
0000920869	REPLACE DAMAGED CEILING TILES THROUGHOUT BUILDING. WHERE EVER POSSIBLE DETERMINE THE CAUSE OF WATER DAMAGE AND REPAIR. TAG WATER DAMAGED TILE FOR REMOVAL FROM BUILDING
0000928095	PURCHASE & REPLACE FIVE SAFETY NET OXYGEN MONITORING SYSTEMS
0000928171	RENEWAL OF MAINTENANCE AGREEMENT FOR RBWARE VIBRATION SOFTWARE AND VIBRATION ANALYZERS
0000928233	REPLACE MICR-PROCESSOR CONTROL BOARD ON CRU0001A
0000934597	REPAIR PH AND ORP SENSORS IN MONITORING EQUIPMENT AT WASTE WATER TREATMENT FACILITY
0000934745	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED (7 PANELS)
0000934752	REMOVE SCALED PAINT, SEAL ROOF JOINTS, PAINT ROOF WALLS. APPROX. 2000 SQ FT BLDG. APPROX. 30,000 SQ FT SURFACE AREA
0000934819	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED (7 PANELS)
0000934921	PERFORM MODIFICATIONS TO THE CHILLED WATER PIPING SYSTEM SO THAT AN AUTOMATIC FAIL OVER TO THE LOCAL CHILLERS WILL OCCUR WHEN THE CENTRAL CHILLED WATER SUPPLY FAILS
0000934924	PERFORM MODIFICATIONS TO THE CHILLED WATER PIPING SYSTEM SO THAT AN AUTOMATIC FAIL-OVER TO THE LOCAL CHILLERS WILL OCCUR WHEN THE CENTRAL CHILLED WATER SUPPLY FAILS
0000934926	PERFORM MODIFICATIONS TO THE CHILLED WATER PIPING SYSTEM SO THAT AN AUTOMATIC FAIL OVER TO THE LOCAL CHILLERS WILL OCCUR WHEN THE CENTRAL CHILLED WATER SUPPLY FAILS
0000934952	PERFORM MODIFICATIONS TO THE CHILLED WATER PIPING SYSTEM SO THAT AN AUTOMATIC FAIL OVER TO THE LOCAL CHILLERS WILL OCCUR WHEN THE CENTRAL CHILLED WATER SUPPLY FAILS

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0000935023	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED (4 PANEL S)
0000935118	REPLACE VENT HOOD FIRE PROTECTION
0000935119	REPLACE VENT HOOD FIRE PROTECTION
0000941015	REPLACE CRU005
0000941126	REPLACE BATTERYPACK THAT ARE ATTACHED TO A GENERATOR THAT SUPPORTS THE MATERIALS DIAGNOSTIC EQUIPMENT IN ROOM 1301 WHEN THERE IS A POWER FAILURE
0000946172	PROVIDE QUOTE TO EXCESS THE FOLLOWING EQUIPMENT, FORGING PRESS, ROLLING MILL, LARGE HAROP FURNACE, LARGE VACUUM INDUCTION FURNACE, PRESSURE INFILTRATION CASTING SYS, SAND BLASTING STATION
0000946541	REPAIR FENCE ON HANDRAILS GOING TO B'MNT ON THE NORTH SIDE OF BWING
0000946583	REPLACE COVE BASEBOARD BEHIND SERVING LINE
0000946612	REMOVE TANKS, PUMPS, SAFETY SHOWER, EYEWASH AND CONTAINMENT STRUCTURE ASSOCIATED WITH OLD DEIONIZED WATER SYSTEM
0000946613	PROVIDE AND INSTALL TWO (2) CHEMICAL "POT FEEDERS" ON THE HOT WATER SYSTEM LOCATED IN ROOM R101/D1 (4610-HWS0001 & 4610-HWS0002)
0000946631	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED (7 PANEL S)
0000946658	INSTALL LIGHTS FOR PARKING LOT WEST END OF BUILDING 4241. LIGHT SURVEY REQUIRED AND AT LEAST SPECIFICATIONS FOR NEW LIGHTS TO BE INSTALLED
0000946685	PROVIDE EMERGENCY SUPPORT TO RESECURE CEILING IN DISPATCH AREA AND OFFICE AREA IN WEST END OF 4312. RESECURE HANGER WIRES IN THE DROP CEILING AREA IN WEST END OF BUILDING
0000953435	REPAIR DAMAGED AREAS OF FOAM ROOF SECTION OF ROOF 10.
0000953507	FABRICATE AND INSTALL SHEET METAL SEAL FLASHING AT THE TOP OF THE SLIDING DOORS BOTH ENDS.
0000953625	REPAIR/REPLACE 17 EA BUILDINGS LIGHTS AND 2EA WEST SIDE PARKING LOT LIGHTS
0000953765	REPLACE EXHAUST FAN ON ROOF SERVING THE 1109 AREA.
0000953850	UPC0001 AND UPC0002 : CLEAN, TORQUE AND REPLACE BAD INSULATORS IN BOTH THESE UPC'S. ANY PART FOUND DEFECTIVE REPAIR OR REPLACE
0000953854	PURCHASE AND INSTALL 120-POWER/PRC12150 BATTERIES TO REPLACE THE ENTIRE BATTERY BANK FOR THE LIEBERT 625KVA UPS
0000953957	PROVIDE UXO SUPPORT FOR TC 920752
0000960275	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED - (26 PANEL S)
0000960279	FABRICATE AND INSTALL NEW GUARDS FOR THE AHU'S
0000960355	REPAIR SAGGING DUCT WORK AND INSTALL ADEQUATE HANGERS TO PREVENT FURTHER DAMAGE TO DUCT.

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0000960449	REPLACE THE SECOND PASS OF TUBES IN THE THREE BOILERS AT BUILDING 4675. EACH BOILER WILL NEED 80 TUBES REPLACED. 78 TWO INCH TUBES AND TWO THREE INCH TUBES. FOR A TOTAL OF 240 TUBES IN ALL WITH LABOR.
0000960477	FABRICATE AND INSTALL PROPER GUARDS ON SAF-1, 2, AND RAF 1, 2, TO REPLACE IMPROPER GUARDS.
0000960646	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED (13 PANELS)
0000960766	REPLACE FAN BEARINGS TO RETURN SYSTEM BACK TO NORMAL OPERATING STATE.
0000967166	REPAIR WATER DAMAGED WALLS IN THE HALLWAY OUTSIDE REDSTONE CREDIT UNION.
0000967209	INSTALL ONE UCS TEMPERATURE SENSOR IN ROOM 111A FED BY CRU0012. UCS WILL FURNISH PARTS. HERSHAL WRIGHT AND TIM AUSTIN FAMILIAR
0000967223	INSTALL OR REPLACE ROLLUP DOOR BUMP STRIP (REQUESTED BY JIM DURHAM)
0000967462	FLUSH HOT WATER SYSTEM IN AWING TO INCLUDE E9 AND E12 HOT WATER SYSTEMS PIPING TO AND THROUGH VAV COILS
0000967502	REPLACE TWO HEAT SINK FANS ON VSC #4
0000972443	DISCONNECT ALL POWER FROM 4553 TO 4514 & 4515
0000972490	REMOVE EXISTING TEMPORARY REPAIRS FROM SOUTH FACADE OF TOWER AND INSTALL FABRICATED REPLACEMENT PANELS
0000972678	REPLACE HOT WATER PUMP.
0000972853	INSTALL OUTLET
0000972864	CHANGE AH6 FILTERS
0000972988	REPLACE ALL FAULTY STEAM TRAPS THROUGHOUT MSFC FACILITIES AS FOUND THROUGH III TRASONIC SURVEY PERFORMED BY PTL PERSONNEL
0000973019	EXCESS FILAMENT WINDER AND REINSTALL NEW MACHINE.
0000973028	REPLACE POWER SUPPLY ON FIRE ALARM
0000973060	REPLACE CARPET IN A SMALL OFFICE.
0000973066	REPLACE THE EXHAUST FAN IN THE SOUTH WALL OF ROOM 1111 WITH A EXTERIOR WALL MOUNT EXHAUST FAN WITH DISCONNECT
0000973112	PERFORM CLEANUP AND REPAIR ACTIVITIES RELATED TO WATER DAMAGE TO EAST END OF BUILDING 4494. THE DAMAGE OCCURRED WHEN THE OVERHEAD SPRINKLER SYSTEM RELEASED WATER THROUGH A FAULTY SPRINKLER HEAD. WORK TO INCLUDE EMERGENCY CLEANUP ACTIVITIES AND REPAIR.
0000973178	CHAMBER FACILITY MAINTENANCE (OPEN ENDED)
0000979614	REPLACE THE DAMAGED WIRE AND OUTLETS

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0000979689	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED - (17 PANELS)
0000979813	PURCHASE 4 STROBOSCOPE INSTRUMENTS FOR MACHINERY MAINTENANCE AND PIT INSPECTIONS
0000981885	UXO SUPPORT TO EXCAVATE & REPAIR 6" CI DRAIN LINE ON WEST SIDE
0000985827	REMOVE PLATES SECURING PIPE SADDLES TO PIPE STANDS. THESE PLATES WERE MOST LIKELY WELDED ON DURING CONSTRUCTION, BUT SHOULD HAVE BEEN REMOVED. AFTER REMOVAL, DRESS AREAS WHERE WELD EXISTED TO MAKE THE STANDS AND THE SADDLES SMOOTH. IN ADDITION,
0000985833	REPLACE SUMP PUMP 4708-SUMP007A AND 4708-SUMP007B IN PIT
0000985913	REPLACE THE DOWN SPOUTS AND PROVIDE PROTECTIVE BARRIERS, WHERE THEY ARE DAMAGED FROM COLLIDING WITH GROUND KEEPING EQUIPMENT. REPAIR/REPLACE UNDERGROUND DRAINS
0000985936	ONE TIME PURCHASE OF CONDENSATE PAN TREATMENT TO BE USED IN CONJUNCTION WITH 365 DAY PM'S ON AIR HANDLERS THROUGHOUT MSEC
0000985940	CONVERT THE EXISTING CHILLED WATER AND STEAM VALVE ACTUATORS ON THE AH 1 & 2 FROM 3 POINT FLOATING CONTROLLED ACTUATORS TO INDUSTRY STANDARD 4-20MA CONTROLLED ACTUATORS
0000985945	PROVIDE COST ESTIMATE FOR THE REPLACEMENT OF 50 SIEMENS MODEL 4700 KW METERS
0000986006	(OPEN ENDED) PROVIDE MANHOURS OF CRAFT LABOR TO SUPPORT ET20 TEST GROUP OPERATIONS AS REQUIRED
0000986016	PROVIDE AND INSTALL REUSABLE INSULATION CAPS FOR STRAINERS AT CENTRAL CHILL WATER PLANT.
0000986153	REPLACE THE 18 BOTTOM TUBES IN THE BOILER AND REPAIR THE REFRACTORY IN THE BACK DOOR ON BOILER #1
0000986163	REMOVE AND REPLACE CWP
0000986186	PROVIDE 2-208 3 PHASE POWER OUTLETS ALONG WEST WALL
0000992438	TO OBTAIN OSHA REQUIRED HORIZONTAL CLEARANCES, CRANE 4493-CRN0001 WILL BE MODIFIED TO REMOVE THE TWO LIFTING LUGS FROM THE WEST SIDE OF THE CRANE'S WEST END TRUCK. ADDITIONALLY, THE HANDRAIL FROM THE CROSSOVER SECTION, REMOVE AND RE-ADD
0000992449	RETRO-FIT RECESSED FLUORESCENT FIXTURES IN RMS 211A, 216A, & 218 WITH ELECTRONIC BALLASTS AND T8 LAMPS
0000997827	REPLACE CONDENSING UNIT
0000998033	REPLACE ROOM AIR CONDITIONER
0000998048	REBUILD CHILL WATER PUMP TO RETURN TO NORMAL OPERATING STATE.
0000998116	UXO SUPPORT FOR EXCAVATION NEEDED TO COMPLETE IDIQ # 846374.
0000998131	INSTALL REMOTE ACCELEROMETERS ON FAN AND MOTOR POINTS TO PERFORM VIBRATION ANALYSIS ON (19) AIR HANDLING UNITS
0000998234	REPLACE UNSIGHTLY STAINED CARPET IN HALLWAYS NEAR AREA OF 300 COURTYARD
0000998294	REPLACE LIEBERT COMPUTER ROOM AIR CONDITIONING SYSTEMS.

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0000998302	REPLACE CPU BOARD FOR FIRE ALARM CONTROL PANEL - MAIN ENTRANCE
0000998303	REPLACE IDNET CARD IN MAIN FIREALARM CONTROL PANEL - BLDG 4190 & 4194
0000998337	PROVIDE ESTIMATE TO BUILD TIME CAPSULE STRUCTURE FOR THE MSFC PARTICIPATION IN THE BICENTENNIAL
0000998378	PROCURE AND INSTALL FILTER SYSTEM FOR PROCESS COOLING WATER, AND CHEMICAL CLEAN ALL PROCESS COOLING WATER PIPE - BLDGS 4205/4209
0000998406	REPLACE TWO TEMPERATURE CONTROL VALVES ON TANK 40 AND 12
0000998411	REPLACE THE DISPLAY MODULE CONTROLLER
0001004628	REPLACE BATTERY BANK FOR THE M-WING UPS PER RECOMMENDATIONS OF BLDG 4663 DATA CENTERS INFRASTRUCTURE STRATEGIES STUDY
0001004651	REPLACE THE ELECTRONIC PNEUMATIC CONTROLLOR
0001004660	REQUIREMENTS FOR THE 2005 ENGINEERING DIRECTORATE AWARDS CELEBRATION
0001004661	NEED WHITE LETTERING ON BANNER "ED AWARDS DAY"
0001004692	REPLACE DOORS TO RM AND INSTALL EQUIPMENT ROOM LOCKS
0001004693	INSTALL 480V PANEL, ONE 480V TO 120/208V 45KVA TRANSFORMER AND ONE 120/208V PANEL PER FIELD DESIGN PROVIDED FROM THE EDS CONTRACTOR - 9TH & 10TH FLOORS
0001004694	LABEL ELECTRICAL PANELS AND BREAKERS TO INDICATE THE FUNCTION OR EQUIPMENT BEING POWERED (4 PANEL)
0001004822	REPLACE SUMP PUMP 13 AND 14 IN PIT
0001004898	REPAIR SOUTH HIBAY DOORS
0001004921	REPLACE STEAM COILS
0001004940	REQUIRES CLEANING TO REMOVE DIRT AND STAINS THAT HAVE ACCUMULATED ON THE VINYL FABRIC.
0001010581	TO SUPPORT NASA TESTING, THE INOPERABLE 1-TON AIR HOIST (4612-HST0001), IN ROOM 1000 OF BUILDING 4612 WILL BE REMOVED AND REPLACED, ON A TEMPORARY BASIS WITH THE 1-TON ELECTRIC CHAIN HOIST ORIGINALLY LOCATED IN ROOM 147 OF BUILDING 4610
0001010705	PAINT BRAIDING EQUIPMENT
0001010730	REPLACE THE DXAC UNIT.
0001010745	EXTERIOR- REPLACE DETERIORATED CONDENSATE RETURN LINE EAST OF BUILDING AND REINSULATE
0001010792	REPLACE TRUE ALERT ADDRESSABLE CONTROLLER CIRCUIT BOARD
0001010980	REPLACE ROLL-UP DOOR #1

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001011004	REBUILD CHILL WATER PUMP TO RETURN TO NORMAL OPERATING STATE.
0001011049	REMOVE OLD POLE'S AND INSTALL NEW POLE'S AND GUY WIRES AND REMOVE OLD AIR TERMINAL
0001011125	PROCURE AND INSTALL A REPLACEMENT 2-TON ELECTRIC CHAIN HOIST FOR HOIST HST0001. THE EXISTING HOIST IS INOPERABLE DUE TO MOTOR WINDING DAMAGE
0001016430	HAVE GENERATOR TECH. TO COME ON SITE TO REPAIR GENERATOR. GENERATOR WILL NOT START IN AUTO. CUMMINS AC GENERATOR SET MOD #VTA28-GS2 SER #1900348315 480V 3-PHASE 900 HP
0001016828	PROCURE HEPA VACUUM AND ACCESSORIES FOR BOILER OPERATIONS
0001016834	REPLACE NINE CONTROL VALVES ACCUATORS, LIMIT SWITCHES AND SOLENOIDS AT WASTE WATER TREATMENT FACILITY
0001016854	LOCATE AND REPAIR REFRIGERANT LEAKS ON 40 TON DXAC SYSTEM [DXAC003 AT 4707]. UNIT IS LOCATED OUTSIDE SOUTH WEST CORNER
0001021066	PROCURE PENETRATING CABLE LUBRICANT FOR APPLICATION (SPRAY) ON WIRE ROPES ASSOC WITH CRANES, DERRICKS & HOISTS LOCATED OUTSIDE OF BLDGS & EXPOSED TO THE WEATHER. THE ADDITION OF THIS LUBRICANT WILL DECREASE OXIDATION & CORROSION
0001021105	REPLACE DEFECTIVE PANEL
0001021204	REPLACE HYDRAMOTOR ACTUATOR THREE WAY VALVE ON #3 BOILERS BURNERFRONT - HOV13A162T171 HYDRAMOTOR ACTUATOR VALVETHREE WAY VALVE 1/2" PIPE SIZE 7 SECOND OPEN/ 1 SECOND CLOSE, 300 PSI MAX 120 VOLT BRONZE BODY
0001021209	REMOVE OLD RAILROAD CROSS TIES, PURCHASE AND INSTALL NEW RAILROAD CROSS TIES DOWN RANGE IN FRONT OF THE TARGET AREA AT MSEC OUTDOOR RANGE
0001021210	REMOVE EXISTING EMERGENCY SHOWER AND EYEWASH UNIT AND CAP OFF PIPING. REPLACE WITH PORTABLE EMERGENCY SHOWER AND EYEWASH UNIT
0001021282	REPLACE AND REROUTE APPROX. 260 FT. POTABLE WATER MAIN FEED LINE
0001021283	REPLACE FUEL FILTERS (32 EA.) AND GASKETS
0001021289	CLEAN GUTTERS ON COVERED WALK WAY IN 4200 COMPLEX
0001021375	REPLACE ROLL-UP DOOR & OPERATOR
0001027668	SUPPORT (b)(4) CONTRACTORS BY SHUTTING OFF POTABLE WATER AT 7AM ON SAT 7/9 AND RETURN TO SERVICE ON SUN 7/10 AND STANDBY TO SUPPORT FOR ANY LEAKS - 4200, 4201 & 4202
0001027750	REPAIR GRUNSFOS PUMP FOR BOILER OPERATIONS
0001027752	REPAIR UNDERGROUND WATER LEAK
0001027754	PURCHASE AND INSTALL 3 BATTERIES FOR UPS SYSTEM
0001027807	REPLACE STEAM TO STEAM HUMIDIFIER ASSOCIATED WITH AH014.
0001027871	CLEAN UP MERCURY SPILL
0001027975	REPAIR OR REPLACE THE 7 EXHAUST FANS ON THE CENTER HIGH BAY ROOF.

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001028020	PERFORM PRECISION FAN BALANCE ON AIR HANDLING UNITS - B-AH0006 MEZZ. AHU, B-AH0019 MEZZ. AHU, B-AH0021 MEZZ. AHU, B-AH0007 MEZZ. AHU, B-AH0022 MEZZ. AHU
0001028059	REPLACE OLD CONTROL AIR COMPRESSOR THAT LEAKS OIL WITH THE NEW COMPRESSOR THAT HAS BEEN REMOVED FROM BUILDING 4727
0001028070	REPLACE DUCT HEATER FOR AIR HANDLER NO.1
0001033257	REPLACE SUMP0001 IN PIT IN E-9.
0001033322	PROVIDE REIMBURSEMENT FOR TOH, TOG, AND TOF MATERIALS THAT EXCEEDED \$500 PER WORK ORDER ON THE ATTACHED LIST
0001033416	INSTALL REMOTE ACCELEROMETERS ON FAN AND MOTOR POINTS TO PERFORM VIBRATION ANALYSIS ON (8) AIR HANDLING UNITS
0001033426	REPLACE THE DIFFERENTIAL PRESSURE TRANSMITTER.
0001033444	REPLACE THE POWER CONVERTOR ON THE VFD ON THE RETURN AIR FAN.
0001033480	CLEAN THERMAL VACUUM CHAMBER AND ATTACHED PIPING AND VALVE. REMOVE SOOT AND DIRT BUILD-UP
0001033523	REPLACE NAVIGATION BEACON LIGHT
0001033531	REPLACE 3 ROOF VENT FANS.
0001033568	REPAIR PIPING LEAKS THROUGHOUT BUILDING. EXTEND ALL EQUIPMENT TO BUILDING DRAINS & REPLACE CEILING TILES
0001033573	REPLACE CONTROL AND MICROPROCESSOR ON LIEBERT MINI MATE AC UNIT.
0001033595	REPLACE THE SECONDARY WATER COLUMN HEAD WITH A MCDONNELL & MILLER PART # 162600 94-M-HD HEAD MECHANISM MANUAL RESET COMBINATION LOW WATER CUT OFF
0001033603	REPLACE THE STEAM HOT WATER CONVERTOR WITH AN ELECTRIC WATER HEATER TO SUPPLY HOT WATER TO THE RESTROOMS AND THE SHOP SINK
0001033634	REMOVE THIS HOIST AND DELIVER IT TO THE CRANE SHOP FOR FURTHER INVESTIGATION AND REPAIRS IF WARRANTED
0001038880	PROVIDE ELECTRICAL & DIESEL MECHANIC SUPPORT FOR STS114 FLIGHT ACTIVITIES AT THE 1138 YARD.
0001038924	REMOVE DXAC UNIT NO LONGER IN USE AND REPAIR HOLE IN WALL
0001039096	REPLACE 4160 VOLT FUSES 3 EA. ON COMPRESSOR LP 4
0001039191	4203 / PENTHOUSE REPLACE VIDEO CARD ON COMMOM ELEVATOR CONTROLLER
0001043538	PROVIDE SUPPORT TO (b)(4) FOR REPLACEMENT OF BUSTED UNDERGROUND WATER LINE IN 4200 AREA
0001043848	MOVE THE FEED FOR PANEL MG-1 FROM T-44 TO T601
0001043942	PURCHASE AND INSTALL AN FM RADIO CONTROLLED WIRELESS CLOCK SYSTEM IN EACH BLDG- 4200, 4201, 4202, 4203, & 4600

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001043959	REPAINT PARKING SPACES AROUND ENTIRE BUILDING AND PARKING LOTS
0001043998	REPLACE THE SINGLE POINT NOZZLE ON THE 3" FILL HOSE AT 4611, GAS FACILITY
0001044209	PROVIDE AND INSTALL CHILLED WATER UNIT TO PROVIDE COOLING FOR ROOM
0001044210	INSTALL NEW FLUORESCENT LIGHT FIXTURE WITH ELECTRONIC BALLAST AND TWO T-8 BULBS IN ROOMS 936, 936R, 940, 940A, 940R AND 950
0001044234	RELOCATE ROME JR. CHAMBER (URGENT MOVE)
0001050472	REMOVE THREE UNITS AND TAKE THEM APART TO CLEAN AND SERVICE THE CONDENSER, EVAPORATOR, AND FAN MOTORS
0001050552	REBUILD CHILL WATER PUMP TO RETURN TO NORMAL OPERATING STATE.
0001050568	INSTALL POT FEEDERS IN THE FOLLOWING LOCATIONS: 4663 RM E2, 4612 RMS E5 & E6, 4583 RM E1, 4570 RMS E1 & E2, 4561 RM E1, 4653 RMS E1 & E2, 4674 RM E2, 4605 RM E1, 4207 BSMT, 4487 RM A001, 4487 RM B001, 4487 RM AB101, 4708 RM B110C
0001050574	REPLACE CHART MOTOR AND POWER BOARDS ON PH MICROPROCESSOR ANALYZER AT MANHOLE 39, PH AND CONDUCTIVITY METER AT TEST LAB AND PH METER AT DI WATER FACILITY
0001050593	REPLACE THE DIFF. PRESS. TRANSMITTER ON THE STEAM STATION.
0001050773	INSTALL VARIABLE FREQUENCY DRIVE ON EXHAUST FAN 9 AND SPACE PRESSURE SENSOR
0001050777	FABRICATE NEW LIGHTWEIGHT BELT/PULLY GUARDS ON SUPPLY AIR FANS 1, 2, 3 ON THE MEZZININE.
0001050826	REPLACE THE HUMIDIFIER ON DXAC0001 THAT IS ABOVE THE CEILING IN ROOM 100.
0001057464	MOVE SPACE STATION ECLSS RACK FROM 4705 TO 4619 - THIS WAS WORKED JULY 28, 2005
0001057479	REPLACE CONDENSOR FAN MOTOR THAT IS ON THE ROOF, AND THE TEMPERTURE -HUMIDITY SENSOR LOCATED IN THE ROOM
0001057651	REPLACE EXISTING OXYGEN SENSORS IN FOLLOWING RMS - 101E-2EA,101-2EA,103-1EA,108A-1EA,108C-1EA,108-1EA,109-1EA,110-1EA,111-1EA 104-2EA,FILL ROOM-1EA. RELOCATE SENSORS TO HEIGHT BETWEEN 42" TO 54"(NUMBER NOT DETERMINED AT THIS TIME)
0001057867	REPLACE THE ROOM AC UNIT.
0001064054	PROVIDE YEARLY ACTIVATION OF ELEVATOR SERVICE TOOL
0001064069	PROVIDE DOVER ELEVATOR TECHNICAL SUPPORT TO DETERMINE FAULTS AND REPAIRS NEEDED TO RETURN SERVICE ELEVATOR #5 AND #3 PASSENGER ELEVATOR TO NORMAL OPERATING SERVICE
0001064073	PROVIDE KONE TECHNICAL SUPPORT TO DETERMINE FAULT WITH # 2 ELEVATOR
0001064086	RESTRIPE ALL ROADS IN THE EAST TEST AREA
0001064095	REPLACE THE CONDENSING UNIT.
0001064214	REPLACE/REPAIR OVERHEAD LIGHTS IN HIGH TRAFFIC AREA

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001064220	MOVED RACK ON AUG 15TH BLDG - 4705-4708 - THIS REQUIRED OVERTIME
0001064232	PROVIDE ELECTRICAL SUPPORT ON 8/24/05 FOR 2005 TECHNOLOGY EXPO
0001064503	FURNISH AND INSTALL THE FOLLOWING TEMPERATURE SENSOR ASSEMBLY IN ROOM 101. CONNECT TO UCS FIBER PANEL IN ROOM 100. INFOSCAN PROGRAMMING WILL BE PROVIDED BY UCS CONTRACTOR
0001070372	PROCURE AND REPLACE REVERSE OSMOSIS FILTERS (21) FOR THE DIONIZED WATER SYSTEM. PROCURE AND REPLACE THREE (3) ONE-INCH (1") AND ONE (1) ONE AND ONE-HALF (1 1/2") PLASTIC VALVES AND SOL ENOIDS
0001070523	REPLACE BUSTED HOT WATER HEATER
0001070530	1. BLOCK OFF CURRENT DOOR TO RM 22E AND INSTALL NEW DOOR ON SOUTH SIDE OF 22E. 2. PROVIDE SMALL REVERSE OSMOSIS FILTRATION SYSTEM AT BLDG 4761
0001070555	HANG SIGNS FOR NASA/ALABAMA A&M UNIVERSITY HIGH SCHOOL SR. DAY 2005
0001070598	REPLACE HALLCALL PUSHBUTTONS (TOTAL OF 28EA), REPLACE CAR DOOR SAFETY ELECTRONIC EYE WITH WATER PROOF EYE (1EA)
0001070689	REPLACE ELECTRICAL LIGHTING PANEL WEST END 4TH FLOOR 5 STORY SECTION AND 5TH FLOOR WEST END, REPAIR CHILL WATER LINE LEAK 5TH FLOOR PENTHOUSE
0001070698	REPLACE EXISTING DELTA F OXYGEN DEFICIENCY SINGLE CHANNEL PANEL
0001076014	PROVIDE DAMAGE ASSESSMENT SUPPORT AT MICHOU D - HURRICANE KATRINA
0001077509	REPLACE THE CHILL WATER DIFFERENTIAL PRESSURE TRANSMITTER
0001077606	SET UP CRANE AND REPAIR FLASHING ON EAST SIDE OF ROOF EDGE BLOWN LOOSE BY HURRICANE KATRINA
0001077670	CAP OFF AN ABANDON OLD BROKEN WATER MAIN AND TAP INTO 1-1/2" WATER LINE INSIDE OF BLDG. RUN NEW 1-1/2" LINE AND FEED THE EXISTING RESTROOMS, WIND TUNNEL WATER TANK & PROCESS PUMP. INSTALL APPROPRIATE ISOLATION VALVES TO ALLOW SHUTOFF OF WATER
0001083794	PROVIDE UXO SUPPORT FOR TC # 1077496 AT 4561 AND TC # 1077720 AT 4667
0001083813	RELOCATE SHIPPING AND RECEIVING EQUIPMENT FROM BLDG 4471 TO BLDG 4631- SEE VIC CORDIER FOR NEW LIST (5626)
0001083847	LOCATE AND REPAIR REFRIGERANT LEAK AT CONDENSING UNIT.
0001083883	REPLACE DAMAGED PARTS ON CRAY UPS IN THE NASA DATA CENTER. (ORDER AND INSTALL)
0001083892	SUPPORT (b)(4) CONTRACTORS ON POTABLE WATER & AIR HANDLER OUTAGE ON 9/10 & 9/11
0001083925	COMPLETE THE REMOVAL OF ITEMS FROM THE SOLAR OBSERVATORY TO (b)(4) CAO AS PART OF THE MOVE OF SD50 TO THE NSSTC (b)(4)
0001083939	REPLACE MOTOR ON FUME EXHAUST SOUTH SIDE OF BUILDING
0001083978	IN SUPPORT OF THE CRANE ERECTION CONTRACTOR PROVIDE LABOR TO LOAD REPLACEMENT CRANE COMPONENTS PRESENTLY STORED IN THE SOUTH HIBAY OF BUILDING 4755 AND TRANSPORT THEM TO THE EAST HIBAY OF BUILDING 4610 FOR INSTALLATION

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001084038	REPLACE SAFETY EYEWASHES EW0001 & EW0002. REPLACE SAFETY SHOWER SH0001. RMS 130 & 150
0001084084	REINSULATE PIPING AROUND CONDENSATE PUMP AND REPLACE ANY DETERIORATED INSULATION IN STEAM PIT
0001084088	REPLACE EXISTING MECHANICAL SAFETY EDGE WITH NEW ELECTRONIC EYE SAFETY EDGE - ALL 5 ELEVATORS
0001087016	4708B-AH20-SAF, FAN ASSY.OUTBOARD BEARING MAKING NOISE REPLACE WORN BEARINGS AND PILLOW BLOCKS ON AH
0001089746	REPLACE 2 WINDOW AC UNITS
0001090503	PROCURE (10) WATER COOLERS, FLUSH VALVES AND TIMERS (MATERIAL ONLY)
0001090504	REPLACE STEAM REGULATOR ,THE REGULATOR IS NON-FUNCTION AT PRESENT TIME
0001090529	REMOVE OIL CONTAMINATED WATER FROM BOTH NORTH & SOUTH COOLING TOWER SUMP PITS.CLEAN BOTH COOLING TOWERS AND SUMP PITS WITH FIRE HOSE. REFILL BOTH SUMP PITS AND RETREAT WITH PROPER CHEMICAL LEVELS
0001092606	REATTACH SIDING TO BUILDING THAT WAS BLOWN LOOSE IN HIGH WINDS. IF SIDING IS DAMAGED, REPLACE WITH NEW SIDING AND PAINT TO EXACT MATCH
0001092612	REPLACE ROLL-UP DOORS # 2,3,4,5,6,7,25
0001095402	MOVE RACK #3 FROM 4705 TO 4619
0001095467	PROVIDE AND INSTALL 5 TON DXAC SYSTEM AND NECESSARY DUCT WORK AND SIR RETURNS TO MAINTAIN TEMPERATURE OF A COMPONENT STORAGE AREA IN BLDG. VALIDATE CRITICAL UCS MONITORING AND CONTROL OF THE NEW INSTALLATION
0001095506	REPAIR AUTOMATIC DOOR ON EAST END OF 4200
0001095769	REPAIR ELECTRICAL CONTROLS TO ALLOW PROPER OPERATION OF SWING-ARM DERRICK ATOP ENGINE TEST STAND 4696 IN THE WEST TEST AREA
0001102118	REPLACE A 60 HP MOTOR ON AIR HANDLER NO. 1
0001102154	REPLACED ONE TUBE IN THE # 1 BOILER AT BUILDING 4567 AND HYDRA TEST TO 150 PSI. THIS IS ON AN 1965 , 300 HP SUPERIOR BOILER
0001102160	INSTALL CARPET IN ROOM
0001102659	MOVE RACK #3 SPACE STATION ECLSS FROM BLDG 4619 TO BLDG 4705. THIS IS PCH AND MAY REQUIRE OVERTIME
0001102679	REPLACE FAN BEARINGS AND MAKE NEEDED REPAIRS TO RETURN SYSTEM BACK TO NORMAL OPERATING STATE
0001105658	MOVE VACUUM CHAMBER FROM RM 110 OF BLDG 4200 TO SAND BLAST FACILITY 4745. RETURN VACUUM CHAMBER WHEN SANDBLAST JOB IS FINISHED
0001110319	REPLACE LEAKING HOT WATER HEATER IN RM.A102 E-1
0001110368	ANTI-FREEZE ALL CHILL WATER AC-SYSTEMS TO WINTERIZE

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001110407	REPLACE ROOM HEAT/COOL UNIT
0001118306	THE BRIDGE RAILS ASSOCIATED WITH CRANES 4619-CRN003 AND 4619-CRN004 IN THE EAST HIBAY REQUIRE RE-ALIGNMENT
0001118415	REPLACE DXAC AIR HANDLER UNIT WHICH FEEDS COMPUTER AREA AT SECURITY BUILDING
0001118416	REPLACE ROOM AC UNIT.
0001118471	FABRICATE 22 MOUNTING BRACKETS FOR SECURITY CAMERAS
0001118495	SUPPORT PREPARATONS FOR ELECTRICAL OUTAGE ON 10/29/05 REFERENCE FWR # 779094
0001118502	LOCATE AND REPAIR CONTROL AIR LEAKS THROUGHOUT THE BUILDING.
0001118503	LOCATE AND REPAIR CONTROL AIR LEAKS THROUGHOUT THE BUILDING.
0001118504	LOCATE AND REPAIR CONTROL AIR LEAKS THROUGHOUT THE BUILDING.
0001118517	REPAIR GRUNSFOS PUMP FOR BOILER OPERATIONS
0001118628	REPLACE THE FOUR SINKS, FAUCETS, TRAPS, AND RISERS
0001118877	PROVIDE UXO SUPPORT FOR STEAM LINE EXCAVATION AT SE CORNER OF 4678
0001118880	REBUILD CHILL WATER PUMP TO RETURN TO NORMAL OPERATING STATE.
0001118955	MODIFY ISOLATION GATE IN COOLING TOWER SUMP TO PROVIDE MORE RELIABLE OPERATION. INSTALL WATER SHED ABOVE GATE TO PROVIDE PERSONEL TO ACCESS GATE AND ACTUATOR WITHOUT DEACTIVATING COOLING SPRAY VALVES
0001120971	REBUILD CHILL WATER PUMP TO RETURN TO NORMAL OPERATING STATE.
0001123765	REPLACE BEARING ON DEFLECTOR SHEAVE ELEVATOR #2 ,ELEVATOR SUB-FLOOR LEVEL
0001123829	SUPPORT (b)(4) (REDSTONE WATER DEPT.) POTABLE WATER OUTAGE NOV. 11th ---- 13 th
0001123830	FLUSH HOT WATER SYSTEM IN 4487 AB, B AND C WINGS 1st & 2nd FLOORS, THROUGH VAV, COILS AND CLEAN STRAINERS
0001123832	PROCURE T LV TM5 TRAPMAN COMPUTERIZED TRAP MANAGEMENT SYSTEM WITH TRAP MANAGER WINDOWS SOFTWARE AND MANUALS TO INCLUDE ON-SITE TRAINING
0001123835	REPLACE 4 AUTOMATIC DOORS
0001123836	REPLACE 3 AUTOMATIC DOORS
0001126771	REPAIR / REPLACE SPENCE STEAM CONTROL VALVES E 1
0001126776	REPAIR LIGHTS -5TH LEVEL OF LTA AREA
0001126851	REROUTE OUTLETS, INSTALL CIRCUIT

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001126855	PROVIDE PRESSURE REGULATOR AND FLEXIBLE AIRLINE BETWEEN THE THERMAL CHAMBER CONTROLLER AND THE SHOP AIR LINE LOCATED ON THE NORTH WALL
0001130026	REPLACE FAULTY STEAM RELIEF VALVE
0001130121	REPLACE AHU MOTOR (MATERAIL ONLY)
0001130353	REPLACE ACMP0001
0001130386	REPAIR CONTROLS FOR CHILLER.
0001130408	REPLACE POWER CONVERTOR
0001132991	REPLACE ROOM AC UNIT
0001135979	PROVIDE LABOR AND MATERIAL TO MODIFY ELECTRICAL FLOOR BOXES TO MEET FACILITIES REQUIREMENTS AND CUSTOMERS NEEDS. ALSO ADDRESS ANY SAFETY ITEM IDENTIFIED DURING SURVEY TO BE PERFORMED BY A S22
0001136192	REPLACE THE TEMPERATURE CONTROLS AND THE MICROPROCESSOR BOARD
0001136466	REPLACE CONDENSATE LINE FROM BASEMENT TO HEADER ABOVE RM. 1212. ABANDON EXISTING LINE IN
0001136480	PROVIDE UXO SUPPORT FOR EXCAVATION
0001136522	INSTALL 2 STAINLESS STEEL 11'X 8' SCREENS WITH A MESH OF 3/8" X 3/8". THE WIRE GAUGE SHOULD BE 25-29 BWG (0.020" - 0.015" DIA) TO ALLOW LEAST HINDERED FLOW OF INDUCED AIR INTO THE COOLING TOWER. THESE WILL BE INSTALLED ON EAST AND WEST SIDES OF
0001139087	REPLACE MOTOR ON AH0001 WITH NEW ENERGY E PLUS
0001142030	PURCHASE AIRCRAFT WARNING LIGHTS - BLDGS 4200,4476,4514,4588,4619,4572,4614,4707,4550,4752, 4670,4696 AND SATURN ROCKET
0001142191	THE BRIDGE RAILS ASSOCIATED WITH CRANES 4705-CRN0001 AND 4705-CRN0002 IN THE MAIN HIBAY OF BUILDING 4705 REQUIRE RE-ALIGNMENT. RE-ALIGNMENT WILL REDUCE PREMATURE BEARING AND WHEEL WEAR ON THE EXISTING CRANES
0001142461	SUPPORT HOLIDAY RECEPTION
0001144602	LABEL THE EMERGENCY PUSH BUTTONS TO WHICH CIRCUIT PANEL THEY ARE ATTACHED TO
0001147676	REBUILD SPENCE TEMPERATURE CONTROL VALVE AND PILOT
0001147776	REPAIR CONTROLLER FOR STEAM STATION
0001147872	REBUILD STEAM REGULATOR AND PILOT VALVE
0001154199	REPAIR CYBEREX SWITCH, HAS SRC 1 BLOWN MOV FUSE ALARM, PROVIDE FACTORY TECH TO SUPPORT REPAIRS
0001154297	INSULATE STEAM PIPING, CONDENSATE PIPING, CHILL WATER PUMPS 1&2, & MOISTURE SEPARATOR.
0001160048	REPLACE THE PNEUMATIC TRANSDUCER

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001160164	PROVIDE UXO SUPPORT FOR IDIQ # 779294, REPLACE AIR VENT VALVES ON THE HPIW SYSTEM.
0001160191	SNOW AND ICE REMOVAL 2005- 2006
0001160597	REPLACE THE PNEUMATIC TRANSDUCER
0001167421	REPAIR/ REPLACE SECTION OF REAR AND FRONT CROWN SHEET BELOW THE FIRE TUNNEL IN THE #3 BOILER
0001173414	CONSTRUCT WEATHER PROTECTION STRUCTURE FOR THE 25 HP PORTABLE BOILER DELOYED AT THE
0001173463	NITROGEN TANKER TRUCK OVERTURNED/ LEAKING DIESEL FUEL AT MARTIN AND DODD ROAD
0001173558	PROVIDE LABOR AND MATERIALS TO CHEMICALLY TREAT THE PROCESS WATER SYSTEMS. PROCURE 8 DRUMS OF SAFE-D-SOAP AND TREAT ONE SYSTEM
0001173566	REPLACE THE EXISTING ROLL-UP DOOR
0001177061	REPLACE COUNTER WEIGHT ROLLERS ON CARS 1, 2, 3, 4 & 5
0001181488	REPAIR DAMAGED WALL
0001188284	REPAIR OPERATION OF OUTSIDE AIR DAMPER.
0001190963	INSTALL VISUAL STROBE LIGHT CONNECTED TO THE FIREALARM SYSTEM AS REQUESTED BY THE SAFETY OFFICE
0001190976	REPLACE THE 15 EA. 20X20X 30 INCH EXTENDED SURFACE 95% POCKET FILTERS
0001195270	REPLACE BUILDING CHILLED WATER VALVE AT 4493.
0001195271	REPLACE THE TWO RESTROOM EXHAUST FANS LOCATED ON ROOF 14 - RMS 135,133,211,209
0001195331	REPLACE THE PRESSURE DIFFERENTIAL TRANSMITER.
0001195431	SUPPORT (b)(4) ON INDUSTRIAL WATER OUTAGE 1/13-1/16 TO REPAIR 36" WATER LINE TO INCLUDE DRAINING AND REFILLING THE FIRE SUPPRESSION SYSTEMS IN ALL BUILDINGS WHERE THE FSS IS FED BY INDUSTRIAL WATER /
0001195446	REBUILD CHILL WATER PUMP TO RETURN TO NORMAL OPERATING STATE.
0001195551	REPLACE EXISTING DELTA F OXYGEN SINGLE CHANNEL SYSTEMS (1EA) WHEN CELL NEEDS REPLACING AS DISCUSSED WITH KEVIN PRIMM
0001195552	REPLACE EXISTING DELTA F OXYGEN SINGLE CHANNEL SYSTEMS (1EA) WHEN CELL NEEDS REPLACING AS DISCUSSED WITH KEVIN PRIMM
0001195553	REPLACE EXISTING DELTA F OXYGEN SINGLE CHANNEL SYSTEMS (1EA) WHEN CELL NEEDS REPLACING AS DISCUSSED WITH KEVIN PRIMM
0001195554	REPLACE EXISTING DELTA F OXYGEN SINGLE CHANNEL SYSTEMS (1EA) WHEN CELL NEEDS REPLACING AS DISCUSSED WITH KEVIN PRIMM
0001195555	REPLACE EXISTING DELTA F OXYGEN SINGLE CHANNEL SYSTEMS (1EA) WHEN CELL NEEDS REPLACING AS DISCUSSED WITH KEVIN PRIMM

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001195577	MAKE 3500 7" X5" WARNING LABELS "ARC FLASH & SHOCK HAZARD - APPROPRIATE PPE REQUIRED". MAKE 3500 5" X 3.5" SAME
0001197902	UXO SUPPORT FOR EXCAVATION AT 4550 IN SUPPORT OF TC 1177051 REPAIRS
0001197911	EXCHANGE BATTERIES BETWEEN HOSC UPS AND 4207 UPS
0001201346	PROVIDE AND INSTALL HVAC UNIT ON 12' x 12' x 12' ENCLOSURE. UNIT MUST BE CAPABLE OF PROVIDE TEMPERATURES IN ENCLOSURE BETWEEN 0F AND 99F. CONTACT KIRCH - 4-5069 FOR DETAILS
0001201354	REPLACE UPS BATTERIES - BLDGS 4542 & 4540
0001201436	REMOVE AND REPLACE CARPET, SHEETROCK WALLS, SEAL NEW CONCRETE BLOCKS ON INSIDE, REPLACE CEILING TILES AND REPAINT AREA IN ROOMS 72 & 73
0001201489	REPAIR BLOWER ASSEMBLY FOR DXAC001 AT BUILDING 4492.
0001201541	INSTALL REMOTE ACCELEROMETERS ON FAN AND MOTOR POINTS TO PERFORM VIBRATION ANALYSIS ON (5) AIR HANDLING UNITS - 4436-AH0001 F-2 4476-AH0009 RM 110R 4491-AH0001 F-1 4491-AH0003 F-4 4491-AH0004 F-1
0001209267	REPLACE 480 VOLT FEEDWIRING, DISCONNECT BREAKER AND DAMAGED CONDUIT
0001209295	REPLACE COOLING TOWER PIT COVERS.
0001209337	REPLACE THE WATER SOFTENER TO THE BOILER WHICH HAS A YEAR ROUND OPERATION.
0001209409	INSTALL 2 ANTENNAS FOR GPS SURVEYING EQUIPMENT - 4241, INSTALL ANTENNA AND GPS REPEATER - 4200, TECH REP WILL BE HERE JAN 26 & 27 2006
0001209411	REPLACE THE ENTIRE BATTERY BANK IN THE MSFC REPOSITORY'S DELTEC UPS BATTERY CABINET. REMOVE AND PROPERLY DISPOSE OF THE OLD BATTERIES
0001209443	PATCH AND PAINT W/GLOSS PAINT OR EPOXY, THE AREAS UNDERNEATH THE PAPER TOWEL DISPENSORS WHERE WATER DAMAGE HAS OCCURRED IN MENS & WOMEN'S ROOMS ON EACH FLOOR
0001209529	REPLACE BUZZING TRANSFORMER AS IDENTIFIED BY (b)(4) REPLACE WIRING FROM PANEL DP-3 PANEL #87 AND RE-ROUTE APPROX 15FT OF CONDUIT ON INCOMING SIDE OF TRANSFORMER
0001213044	REPLACE THE HUMIDITY SENSORS IN EACH ROOM.
0001213050	PURCHASE COMPUTER DRIVEN ROTARY ENGRAVER.. PRODUCT DATA SHEETS WILL BE PROVIDED TO AS-24 FOR REVIEW PRIOR TO PROCUREMENT ACTIONS
0001217051	REPAIR SLUDGE DRYER SYSTEM
0001217156	REMOVE/INSTALL A NEW FRESH AIR INTAKE HOOD ON CURB LOCATED ON ROOF 4
0001217157	PRESSURE WASH SIDE WALK AROUND BLDG. AND STRIPE PARKING LOT AROUND BLDG.
0001217179	REPLACE CONTROL VALVES ON TWO OF THE STEAM UNITS
0001217285	INSTALL REMOTE ACCELEROMETERS ON FAN AND MOTOR POINTS TO PERFORM VIBRATION ANALYSIS ON (6) AIR HANDLING UNITS. - 4755-EAF0001, 4755-EAF0002, 4755-AH0015 N. HIBAY, 4755-AH0026 N.HIBAY, 4755-AH0025 N.HIBAY, 4755-AH0024 N.HIBAY

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001217286	INSTALL REMOTE ACCELEROMETERS ON FAN AND MOTOR POINTS TO PERFORM VIBRATION ANALYSIS ON (7) AIR HANDLING UNITS. 4705-AH0001 E-11, 4705-AH0026 E.Hall, 4705-AH0037 OVER TOOL RM, 4705-AH019A E-15, 4705-AH010B E-15 4705-AH0002 SUPERV 4705-AH0044 RM100
0001217288	INSTALL REMOTE ACCELEROMETERS ON FAN AND MOTOR POINTS TO PERFORM VIBRATION ANALYSIS ON (3) AIR HANDLING UNITS - AH0023 MEZZ 4707-EAF0007 2ND LEVEL 4707-AH0007 RM 106
0001217290	INSTALL REMOTE ACCELEROMETERS ON FAN AND MOTOR POINTS TO PERFORM VIBRATION ANALYSIS ON (4) AIR HANDLING UNITS - 4718-AH0004 E-2 4718-AH0001 E-5 4718-1-AH0006 E-1 4708-AH0012 RM 105 OVERHEAD
0001217320	REPLACE DEFECTIVE STEAM ACTUATOR
0001220312	REPLACE EXISTING DELTA F OXYGEN SINGLE CHANNEL SYSTEMS (1EA) WHEN CELL NEEDS REPLACING AS DISCUSSED WITH KEVIN PRIMM
0001224624	REPLACE STARTER ON AIR COMPRESSOR
0001224693	REPLACE MOTOR BEARINGS AND/OR MOTOR. REPLACE FAN BEARINGS.
0001231222	SUPPORT THE SUPER GUPPY OPERATIONS AT REDSTONE AIRFIELD AND AT 4755
0001231451	REPLACE TWO KEYSTONE WAFFER CHECK VALVES.
0001231468	REPAIR BLOWER SHAFT IN DXAC001.
0001231498	REPLACE THE STEAM PRESSURE TRANSMITTER.
0001231499	REPLACE 40 HP MOTOR
0001231581	PRESSURE WASH ALL WALKWAYS AROUND BLDG.
0001235205	REPLACED THE PNEUMATIC TRANSDUCER, AND DIFF. PRESSURE TRANSDUCER.
0001238969	RELOCATE STEAM PRESSURE TRANSMITTER FROM OUTSIDE AT THE STEAM STATION TO INSIDE E-4 EQUIPMENT ROOM
0001247776	REPAIR AUTOMATIC DOORS EAST END 4200.
0001247967	PURCHASE AND DELIVER A 100HP PORTABLE BOILER. THIS BOILER WILL BE MOUNTED IN AN ENCLOSED TRAILER THE PURCHASE WILL INCLUDE THE WATER SOFTENER CHEMICAL FEED AND BLOWDOWN
0001247983	UXO SUPPORT FOR EXCAVATION AT 4673 TO SET POLES UNDER 1011049.
0001251066	REPLACE THE 7.5 TON COMPRESSOR ON THE CONDENSING UNIT AND REPAIR SMALL LEAKS IN THE SYSTEM
0001253985	REPLACE BOTH STEAM CYLINDERS
0001254171	RODDED THE CONDENSOR AND EVAPORATOR ON THE CHILLER.
0001254172	ROD CONDENSOR AND EVAPORATOR ON CHILLER #5
0001254181	REPLACE GROUNDED COMPRESSOR ON DXAC SYSTEM
0001256822	REPAIR AIR HANDLER IN ELEVATOR MACHINE RM (TAYLOR)

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001256829	REPLACE THE MAIN PC BOARD
0001256853	THE PENDANT ASSEMBLY ON OVERHEAD HOIST (HST-0001) IS DEFECTIVE IN BLDG. 4760. PROVIDE LABOR AND MATERIAL REQUIRED TO REPLACE EXISTING PENDANT CONTROL
0001256914	MEASURE AIR FLOW, CHECK AND CLEAN MIXING BOX, DIFFUSERS AND REPLACE FLEX DUCT FROM BOX TO DIFFUSERS
0001256920	REPAIR PUMP FOR AIR DRYER.
0001256941	REPLACE THE COMPRESSOR , REFRIGERANT AND DRIERS.
0001259757	REPLACE FUEL OIL METER ON THE BOILER FRONT. PARTS ONLY LABOR DONE BY BOILER PERSONNEL.
0001259850	PROVIDE FOR THE RELOCATION OF LOW-PRESSURE SENSOR PORTS FOR SPACE PRESSURE SENSORS LISTED BELOW. THE EXISTING PORTS, WHICH ARE LOCATED WITHIN THE BUILDING, MUST BE CONNECTED TO AN OUTSIDE AIR REFERENCE
0001259942	REPLACE THE CONDENSING UNIT, AND BOTH DRIERS.
0001260133	INSTALL GUARDS ENCLOSURES TO PREVENT INADVERTENT CONTACT WITH ALL MOVING PARTS(SUCH AS PULLEYS SHAFTS GEARS AND OTHER PINCH POINTS) DRIVE BELTS 4755-AH11 20 40 41
0001260156	REPLACE THE MAIN CONTROL BOARD.
0001260188	REPLACE INBOARD AND OUTBOARD BEARINGS, MOTOR SHEAVES, FAN SHEAVES, REPLACE BELTS, ALIGN AND SET TENSION
0001267274	PURCHASE AND STORE 500 BOXES OF 24X24 CARPET TILES
0001267354	REPLACE THE DXAC UNIT THAT FEEDS THE ELEVATOR EQUIPMENT ROOM.
0001267358	REPLACE CPU BOARD ON 4002 FIREALARM CONTROL PANEL (MATERAIL ONLY)
0001267637	REPLACE 20 GAL. HOT WATER HEATER (ABOVE FOYER)
0001267654	REMOVE (3) LEKTRIVER FILE SYSTEMS AND TAKE TO EXCESS- DISASSEMBLE FILE SYSTEM, REPLACE CEILING GRID AND TILE
0001274712	MOVE THE 4 ROTATING FILES IN 4566- RM154A & 4485-RM 128
0001274714	REPAINT SYMBOL OF ACCESSIBILITY ON PAVEMENT FOR 15 HANDICAP PARKING SPACES LOCATED AT THE NORTH FRONT ENTRANCE OF 4708 - AND 5 ON THE EAST SIDE OF BLDG
0001274822	REPAIR CHILLER. REMOVE REMAINING REFRIGERANT, REPAIR LEAK AT RUPTURE DISK, LEAK CHECK CHILLER AND RECHARGE SYSTEM
0001274844	4610 GENERATOR LEAKING FUEL BALETINE CHECKING CALLED IN BY LARFARLETT
0001281493	REPLACE THE CONDENSING UNIT.
0001281588	REPLACE FAN BEARINGS AND MAKE NEEDED REPAIRS TO RETURN SYSTEM BACK TO NORMAL OPERATING STATE

IDIQ Historical Workload 7/1/05 - 6/30/06

WORK ORDER	DESCRIPTION
0001281669	RECONFIGURE STEAM PIT TO ELIMINATE THE ABANDON CONDENSATE RETURN PUMP. REPLACE ALL SECONDARY PIPING, VALVES & INSULATION. REBUILD THE ABOVE GROUND CONDENSATE PUMP. REPLACE VALVES, PIPING & INSULATION & ADD A PRESSURE REDUCING VALVE AT CONDENSATE PUMP.
0001284419	ROD OUT CONDENSERS AND EVAPORATORS ON CHILLERS 1, 2, 3, 6, 7, 8, & 9
0001287222	INSTALL 2 WIRELESS CLOCKS
0001287871	PROVIDE UXO SUPPORT FOR TC 1274692 (INSTALL GROUNDING ROD, NEXT TO TEST STAND 115)
0001300853	REPLACE AIR HANDLER MOTOR WITH NEW E PLUS MOTOR
0001300960	REPLACE TUBE BUNDLE
0001301229	PROVIDE ELECTRICAL SUPPORT FOR THE CIO TECHNOLOGY AWARENESS CAMPAIGN ON 5/3/06
0001304521	PROVIDE UXO SUPPORT FOR EXCAVATION AT 4675
0001307546	PERFORM A RATE LOAD TEST OF THE HARVICK 9' x 12' AUTOCLAVE PER THE ATTACHED EM40-OWI-028 REVISION F
0001307556	PROVIDE ELEVATOR SUPPORT ON SITE AS REQUESTED
0001307694	REPLACE BAD 250 AMP MAIN BREAKER FOR MCC IN ROOM AB-103
0001313820	REPLACE BURNER ASSEMBLY AND DIFFUSER ASSEMBLY ON BOILER #1
0001326880	ERECTED SCAFFOLD AND INSTALLED TEMPORARY ROPE WITH SNAPS SO FLAG COULD BE RAISED AND LOWERED. WIRE CORE FLAG ROPE WILL BE INSTALLED WHEN MATERIAL IS RECEIVED PR-2818.
0001332986	PROCURE AND REPLACE ONE COMPRESSOR
0001335753	SUPPORT ARMY'S & (b)(4) ELECTRIC'S INSTALLATION OF MAIN BLDG POWER.
0001337931	PROVIDE UXO SUPPORT IN SUPPORT OF WORK ORDER #1313832 TO DIG UP WATER LINE
0001337992	APPLY ELASTOMERIC COATING TO ROOF APPROXIMATELY 2800 SQ. FT.